


S.A.M.S. - SHALLOW ANGLE MINING SYSTEM



- 1)** Haulage drift (access)
- 2)** Start out bay (alcove, cut-out)
- 3)** Draw point
- 4)** Opening drift (draise)
- 5)** Stope ore